

FIGURE 1




FIGURE 2





FIGURE 3



A bar chart illustrating the percentage removal of a substance across four pH levels (pH2, pH4, pH6, pH8) for nine different materials. The y-axis represents '% Removal' ranging from -20 to 120. The x-axis shows the pH levels. A legend on the right identifies the materials by their bar patterns: PEI (horizontal lines), PEI-A (grid), PEI-E (vertical lines), PEI-p52-1 (cross-hatch), PEI-p52-2 (dotted), PEI-P (diagonal lines \), PEI-2P (diagonal lines /), PEI-2C (wavy lines), and PEI-PC (chevron).

pH	PEI	PEI-A	PEI-E	PEI-p52-1	PEI-p52-2	PEI-P	PEI-2P	PEI-2C	PEI-PC
pH2	-5	2	-18	-10	-10	-1	-1	-10	5
pH4	-3	-1	71	4	11	-2	4	5	52
pH6	20	97	94	58	91	93	98	99	94
pH8	101	100	100	101	101	101	101	101	101

FIGURE 5




FIGURE 6




FIGURE 7




FIGURE 8

